## For Style 1206P24 Assembly Instruction Sheet #IS-1206P24

STEP 4 - Wire Conta


Install Celling Canopy to Celling

oole Required: Fatheed screwdiver, Philips screwdiver, pliers, wire culters, who stippers, electrical tape, safety glasses. (b) 120V LED "I'W DIMAABLE (30000') with deserver (b) 120V LED "I'W DIMAABLE (30000') when the state of the secondry Time: 19-20 minutes represent the secondry Time: 19-20 minutes are represent the secondry Time: 19-20 minutes are represent the secondry times and prefer beginning installation. Check package content list and diagrams below to be sure all parts are market. If any parts are minutegr or damaged, do not alternot to exercise, install, or operate the titude. Context customer service for explanament.

## **△Warnings and Cautions**

Turn off electricity at circuit breaker or main fuse box before installation. Consult a licensed electricism if in doubt. These instructions are provided for your safety. It is very important you read them completely before installing the tidure. We strongly recommend that a licensed, professional electricism perform the installation.

Disconnect fixture from power source before repiscing builbs. Make sure builts are given sufficient time to cool before removed



A. Pase the supply wires through the Crossber (EE).

Attach the Crossber (EE) to the Outlet Box (CC) STEP 2 - Attach Croseber to Outlet Box. with the head of the Green Ground Screw facing you.
Secure It with Outlet Box Bareins (not included). griten undi anug Supply Wires with Outlet Box Screws Ground Wire 8 **Outlet Box** Ħ

Hardware Contents DESCRIPTION PILLINATION

**#88** ₹ **Outlet Box Screw** founding Screw 8

STEP 3 — Fit Calling Canopy to Crossber Assembly

Figure 2

e, Lock Weehen deuto Capaci 8 A. Fit the ceiling carnopy to Mounting Screwe (DD) and secure with Mounting Balls (AA). Note: The ceiling carnopy should be enug against the ceiling and the Mounting Balls (AA). orrect length is achieved. hen screwing Mounting Idrews (DD) in or out of the mecrewing the Hex Nut and Lock Washer and f not, adjust the length of the ounting Screws (DD) by ber (EE) until the

and Hex Nuts to Crossbar.

A. Line up a set of holes on the
Crossbar (EE) and Holes

ne ceing caropy. read Mounting Screwe (DD) the holes on the ver (EE). Pees Lock ves and thread Hex

fund fighten until enug Jule onto the Mounting


Figure 1

Figure 3

Once the ceiling canopy is secure, remove the Mounting Ball (AA) and ceiling canopy and proceed to Step 4. 8

> A. Use standard wire connectors (not included) to make all wire connectors until wires are tigritly joined together. What connections with approved electrical type and commendom with approved electrical type and carefully staff all the connection where into the Outlet Box. from outlet box outlet box (or Red) Black wire from White wire White wire from fixture from flature Black wire

A. Garefully track all whee into the outlet box and position the ceiling campy of the Foture Body (A) over the outlet box. Algo the holes in the ceiling campy with the Mounting Screen (DD).
Secure with Mounting Balls (AA) and hand dighten until easy. Ceiling Canopy 8



from outlet box Bare, or Green from outlet box Bans, or Greet Ground wire Ground wire Figure 4 on the Crossbur Green Ground Screw Ground wire from fodure from fixture

Figure 5

1 of 2

ReleasedDate:2019-04-16