For Style 8318P36C-16+8+1 Assembly Instruction Sheet #S-8318P36C-16+8+1

s Requited: Falfred screwither, Phillips screwither, plien, who culture, who shippers, electrical tupe, authly glasses. Source: (25) Candelsion Bees Batts 60W Machinum. Selected (25) Candelsion Bees Batts 60W Machinum. I are the standly of the selected prints before beginning installation. Check puckage content list and diagrams below to be sure all parts are still any parts are missing or damaged, do not attempt to assemble, Install, or operate the Source. Contact customer service for replacement


⚠ Warnings and Cautions

Turn off electricity at circuit breaker or main fuse box before installation. Consult a licensed electricien if in doubt.

These instructions are provided for your safety. It is very important you read them completely before installing the folium.

We strongly recommend that a licensed, professional electrician perform the installation.

Disconnect theture from power source before replacing buttle. Make sure buttle are given sufficient time to cool before removal. A.(Refer to SUPPORT ARMS DISTRIBUTION) Page supply STEP 1 Install Support Arms




STEP 2 -Install Cap, Crystal Cap and Fbdure Loope
A Pass supply wire and ground wire through the plate
with coupling.
Support Wire Ampport import Wire -bdure Loop te with Coupling Refer to Wire AT NUT

Allippie with Hex Nut -Ribbed side of supply wire from Support Arms Identified with the label "N" Identified with the label "N" Crystal Cover -Smooth side of supply wire H from Support Arms Identified with the label "L" Identified with the label "L" Circular tube -Ė Figure 2 Smooth side of wire Supply Wires Mire Nut Refer to Wire Plate with Social

> C. Thesaid the hext raid end of the nitppie with hext raid into the hext coupling on the piete with acolast. By using piete, thread the hext at against the hext coupling and hext digition until entury. Pleas a sordier cover, crysial cover end cap over the end of the nitppie with hext raid. Secure them with enother this! B. Thread one end of the hipple into the coupling on the plate with coupling.
>
> Place one cover, one crystal cover and one cap over the end of the nipple and onto the top center of the plate with coupling


STEP 3 - Install the Crossber to the Calling

A. Place the creature to the celling and make (4) make from the hotel of the creature on the celling for anchors. Remove the creature and diff proper hotel from the (4) make for anchors. B. Insert anchors into drilled hotel property. Place the creature; ts. t.



STEP 4 - Install Chain System and Fixture Body togethe

- Remove the bolt from the quick connector. Place the quick connector onto the chain link of the bottom and of the chain system.
- Place the Status loop helds of the quick connector. Thread the bolt back onto the quick connector and the Status loop. Hand Sprian unit snug to connector the chain system to the Status.



Black wire from outlet box (or Red)

Smooth side of wire from fature identified with the label "L"


Ribbed side of who from fidure identified with the Label "N"

White wire from outlet box

STEP 6 - Making the Wire Connections A. Use standard wire connectors (not included) to make all wire connections. Twist connectors unit when are fighty Figure 5

nto outlet box. oined together. Wrap each connection with approved sectrical tape and carefully stuff all the connected wires

Note: If the electrical wire is going to be cut shorter than provided you will need to identify the "L" the wire and the "N" neutral wire before you cut the excess whe off. One to inabeled N and the other labeled L. To do this apparatus the "L" line wire and the "N" neutral wire as far as you and not on the exces the cut. Be sure to mark the wire on the side of the tidure need to. Re-label the wire near where you want to make wire being cut and removed.



SUPPLY WIRES DISTRIBUTION

IRE CONNECTIONS

Figure 1

- Remove the bolt from the quick connector. Place the quick connector onto the hook of the cruebbr. I need the loop on the top end of the chain system halds of the quick connector. Thread the bolt back cris the quick connector and through the loop of the chain pulck connector and through the loop of the chain system. Hand tighten until anug to heng the foture
- Refer to Step 6 for wire connection instructions.
- ည် ၁ the ceiling canopy until anug to secure the ceiling Lift the ceiling canopy upward, over the crossbar, attach onto the ceiling. Using acrewdriver, thread set acrew on

