Assembly Instruction Sheet #IS-1154W11 For Style 1154W11


Tools Required: Flatheed acrewidther, Philips screwidther, pilers, who culturs, who elippers, electrical taps, safety glass.
Light Source: (3) G8 40W Maximum (Not Include).
Estimated Assembly Time: 15-30 minutes

Estimated Assembly Time: 15-30 minutes Properation: Identify and inspect all parts before beginning installation. Check package content list and diagrams below to be sure all parts are present. If any parts are missing or demaged, do not attempt to assemble, install, or operate the Sidure. Contect customer services for replacement


▲ Warnings and Cautions Tun of shortchy at chart breaker or

Ium off electricity at circuit breater or main fuse box before installation. Consult a licensed electrician if in doubt, these instructions are provided for your safety. It is very important you read them completely before installing the fixture. We strongly recommend that a licensed, professional electrician perform the installation.

Disconnect fixture from power source before replacing bulbs. Make sure bulbs are given sufficient time to cool before removal.



ecure with Cap nut (AA) and hand tighten until enug






Figure 7