MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W





WARNING — THE INSTALLATION MUST BE CARRIED OUT BY A QUALIFIED ELECTRICIAN.

- 1. LED Strip lights are suitable for using in dry and damp locations
- 2. Please keep the LED Strip lights away from any corrosive substance, and please use dry cloth when you clean it.
- 3. LED Strip lights can only be installed by a qualified electrician
- 4. Before installation or maintenance, please disconnect the power to prevent electric shock
- 5. DO NOT cover fixture with insulation liner Or similar material.


CAUTION


PLEASE READ INSTRUCTION BEFORE COMMENCING INSTALLATION AND RETAIN FOR FUTURE REFERENCES. Electrical products can cause death or injury, or damage to property.

If in any doubt about the installation or use of this product, consult a competent electrician.


L-CONN INSTALLATION

1. Remove the cover from the L-Connector







3. Slide the splicing bracket B into locating piece, then loci it with screws.



4. Make the mounting marks on the ceiling for fixtures, please refer to pendant mounting for suspending the fixture.



5. Adjust the lifting bracket in the fixture to a suitable position for suspending and linking.



BOX CONTENTS




L-CONNECTOR



SCREWS



SPLICING BRACKET B




- 1. If dimming is not used, please separate the dimming wires with nuts.
- 2. Wiring must follow up the wiring diagram. 3. Remind again: Cut off the power supply before operation.

Instruction Manual


MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W

L-CONN INSTALLATION


6. Insert the L-Connector into the fixtures as shown below, and pull the lock buckle to splice fixtures.



7. Make electrical connection of fixture and X-Connector with male-female connectors.



8. Cut off the connectors in one of the ends for wiring to line voltage.




MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W


Instruction Manual

L-CONN INSTALLATION


9. Screw back the cover of L-Connector, lock back the fixture upper cover, lock back the other end of fixture upper cover.



10. Wire fixtures according to wiring diagram.



11. Installation complete.




CRTECH

MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W


Instruction Manual

L-CONN INSTALLATION

WIRING





INPUT WIRING GROUP (OPTIONAL)



1. Wire according to the wiring diagram on the left for completion.

- 1. If dimming is not used, please separate the dimming wires with nuts.
- 2. Wiring must follow up the wiring diagram.
- 3. Remind again: Cut off the power supply before operation





THREE TERMINALS: NEUTRAL WIRE, LIVE WIRE, GROUND WIRE.
TWO TERMINAL: DIM+ (PURPLE), DIM- (PINK)

ONTECH


MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W


Instruction Manual

T-CONN INSTALLATION


INSTRUCTIONS

1. Remove the cover from the T-Connector.







3. Slide the splicing bracket B into locating piece, then loci it with screws.




4. Make the mounting marks on the ceiling for fixtures, please refer to pendant mounting for suspending the fixture.



5. Adjust the lifting bracket in the fixture to a suitable position for suspending and linking.




BOX CONTENTS




T-CONNECTOR



SCREW:



SPLICING BRACKET B




- 1. If dimming is not used, please separate the dimming wires with nuts.
- 2. Wiring must follow up the wiring diagram.
- 3. Remind again: Cut off the power supply before operation.

MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W


Instruction Manual

T-CONN INSTALLATION


6. Insert the L-Connector into the fixtures as shown below, and pull the lock buckle to splice fixtures.



7. Make electrical connection of fixture and T-Connector with male-female connectors.



8. Cut off the connectors in one of the ends for wiring to line voltage.




Instruction Manual


MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W

T-CONN INSTALLATION


9. Screw back the cover of T-Connector, lock back the fixture upper cover, lock back the other end of fixture upper cover.



10. Wire fixtures according to wiring diagram.




17. Installation complete.




MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W

Instruction Manual

V-CONN INSTALLATION





BOX CONTENTS






"V"joiner




Splicing bracket B





Make the mounting marks on the ceiling for fixtures, pleas refer to pendant mounting instructions for suspending the fixture




CRTECH

MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W

Instruction Manual


V-CONN INSTALLATION



Three-position quick connectors(Yellow): BLACK (LINE)
WHITE (NEUTRAL)
GREEN(GRD)

Two-position quick connectors(Orange): PURPLE (DIM +)
PINK (DIM -)

Three-position quick connectors(White):
The splice connects to the terminal.





CRTECH


MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W


Instruction Manual

V-CONN INSTALLATION










MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W




X-CONN INSTALLATION

INSTRUCTIONS


1. Remove the cover from the X-Connector.




2. Remove the end cap and upper cover from fixture.




3. Slide the splicing bracket B into locating piece, then loci it with screws.



4. Make the mounting marks on the ceiling for fixtures, please refer to pendant mounting for suspending the fixture.



5. Adjust the lifting bracket in the fixture to a suitable position for suspending and linking.



BOX CONTENTS




X-CONNECTOR



SCREWS



SPLICING BRACKET B




- 1. If dimming is not used, please separate the dimming wires with nuts.
- 2. Wiring must follow up the wiring diagram. 3. Remind again: Cut off the power supply before operation.

Instruction Manual


X-CONN INSTALLATION

6. Insert the X-Connector into the fixtures as shown below, and pull the lock buckle to splice fixtures.


MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W



7. Make electrical connection of fixture and X-Connector with male-female connectors.



8. Cut off the connectors in one of the ends for wiring to line voltage.




Instruction Manual


MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W

X-CONN INSTALLATION


9. Screw back the cover of X-Connector, lock back the fixture upper cover, lock back the other end of fixture upper cover.



10. Wire fixtures according to wiring diagram.




11. Installation complete.





MODEL 2ALS-3CCT+W | 4ALS-3CCT+W | 8ALS-3CCT+W

Instruction Manual


END CAP WITH SENSOR INSTALLATION














End-cap Sensor Module

BOX CONTENTS

5 Connect the wires of the same color through male-female connectors or wire nuts







Reference	QTY.	Remarks	Project:
			Location:
			Architect:
			Engineer:
			Contractor:
			Submitted by:
			Date:

ORTECH reserves the right to modify at any time, without notice, any or all of our product's features, designs, components and specifications to meet market changes.