

INSTALLATION INSTRUCTIONS

CAUTION: before starting the installation, disconnected the power by turning off the circuit breaker or by removing the fuse at the fuse box. Turning the power off using the light switch is not sufficient to prevent electrical shock.

1. Remove fixture and parts packages from carton.
2. Thread nipple(1) or screws(A) into crossbar part way. Mount crossbar (2) to outlet box with outlet box screws(3) provided with your outlet box.
3. Connect the white wires from the fixture to white of the supply circuit. Connect the black wires from the fixture to black wire of the supply circuit. Connect the bare copper wire to grounding connector of the supply circuit.

CAUTION: Be certain that no bare wire stands are exposed outside of wire connectors(4).

4. Raise fixture up to ceiling allow nipple (or screws) to protrude thru hole (holes) in canopy (5) and secured by decorative knob (6). Be certain that all wires are safely tucked inside canopy.
5. Install bulbs, refer to relamping label recommended maximum wattage, do not exceed recommended wattage.

