


a Naquinet: Plafinad szendiker, Philips szendiker, pilon, vine cultura, wire alóppera, electrical lapa, salály glasses. 18 deures: (1) SUGGESTED LED OS BILLS MAX 2W (Not include). 19 deures: (1) SUGGESTED LED OS BILLS MAX 2W (Not include). 19 deures: (1) SUGGESTED LED OS BILLS MAX 2W (Not include). 19 deures: (1) SUGGESTED LED OS BILLS MAX 2W (Not include).

These instructions are provided for your safety. It is very important you read them completely before installing the tixture. We strongly recommend that a licensed, professional electricism perform the installation. ium off electricity at circuit breaker or main fuse box before installation. Consult a licensed electricism if in doubt.

Disconnect fixture from power source before replacing bufbs. Make sure bufbs are given sufficient time to cool before removal



A. Pass the supply wires through the Mounting STEP 2 — Attach Mounting bracket to Outlet Box bracket (EE). Attach the Mounting bracket (EE) to the Outlet Box with the head of the Green Ground icrews (OC). Tighten until enug. Screw facing you. Secure it with Outlet Box Supply Wires with Outlet Box Screws Ground Wire **Outlet Box** H 8

STEP 8 — Fit Calling Canopy to Mounting bracket Assess Figure 2

A. Fit the Ceiling Canopy to Mounting Screws (DD) and escure with Decorative Cape (AA). Note: The Ceiling Canopy should be enug against the ceiling and the Decorative Cape (AA). not, adjust the length of the






Figure 3

Figure 6