


colo Requiset: Plafead servediver, Pfilips servediver, plera, who cultura, who shippera, electrical lape, astely glasses light Source: (1) 120Y LED "I W DIMMABLE (4000K.). Minedad Assessibly Thes: 16-50 minutes


Papardos: Identify and haped all parts before beginning heidaldon. Check pedrage content let and degrams below to be sere all parts are resent. If any parts are missing or damaged, do not alternat to assemble, invital, or operate the toture. Content customer service for explanament. Lets.

## ▲ Warnings and Cautions Turn of electricity at circuit breaker or

Turn off electricity at circuit breaker or main fuee box before installation. Consult a licensed electricisn if in doubt. These instructions are provided for your safety. It is very important you read them completely before installing the focuse. We strongly recommend that a licensed, professional electricisn perform the installation.

Disconnect fixture from power source before replacing bubbs. Make sure bubbs are given sufficient time to cool before removal.





2 of 2